

PRODUCT OVERVIEW

Features:

- With stainless steel body and molds, very durable
- Air cooling or Water cooling for your option
- Can set automatically temperature Electronic control
- Different capacity, shape molds for your choice
- With the strength of Speed cooling, high production
- Very easy to operate and maintain
- With Manual and Videos to teach how to operate the machines



Operation steps:

1. Put clean water, then put sea salt(the content is 3:1)
2. Press"On" switch, wait until the temperature goes down to -12 to -15°C
3. Put mixture into Popsicle mold, then put into the cooling container of the machine
4. Wait 15-20mins, then take out the popsicle mold
5. Wait 2mins, then take out popsicles from the mold