General

Operating temperature

 0° C to $+40^{\circ}$ C

Storage temperature

-20°C to +60°C

Operating humidity

0% to 90% (without condensation)

Storage humidity

0% to 90% (without condensation)

Dimensions(W/H/L)

Approx. 256 x 315 x 413 mm(10 x 12.4 x 16.2 inches)

Mass.

Approx. 13kg (28.6 lb)